

Work Per	mit # SJ - 2005 -	198
Work Ord		105-009
Job#	Activity#	

ork requester fills out this section.	☐ Standir	ng Work Permit)		
Requester: Don Lynch	Date: 12/9/05	Ext.: 2253	Dept/Div/Group: I	PO/Phenix	
Other Contact person (if different from	requester): Sal Marino		Ext.: 3704		
Work Control Coordinator: Don Lynch	ı	Start Date: 12/12/05	Est. End Date: 2/	28/05 06	
Brief Description of Work: Inspect and	d/or repair FEM's inside South Muon	Magnet (MMS)			
Building: 1008	Room: IR	Equipment: n/a	Service Provider:	PHENIX	
C, Requester/Designee, Service Pro-	vider, and ES&H (as necessary) fil	Il out this section or attach ana	lysis		
ES&H ANALYSIS					
Radiation Concerns	None	Airborne	☐ Contamination	Radiation	
Radiation Generating Devices:	Radiography	☐Moisture Density Gauges	☐ Soil Density Gauges	☐X-ray Equipment	
☐ Special nuclear materials involved	ed, notify Isotope Special Materials	Group ·	☐ Fissionable materials	s involved, notify Laboratory Critica	lity Officer
Safety Concerns	□ None	☐ Ergonomics	☐ Transport of Haz/Ra	d Material	
☐ Adding/Removing Walls or Roof	© Confined Space*2A	☐ Explosives	☐ Lead*	☐ Penetrating Fire W	/alls
Adding/Nemoving Walls of Nool	□ Corrosive	☐ Flammable	☐ Magnetic Field*	☐ Pressurized Syste	ms
☐ Asbestos*	☐ Cryogenic	☐ Fumes/Mist/Dust*	☐ Material Handling	☐ Rigging/Critical Lif	t
☐ Beryllium*	☐ Electrical	☐ Heat/Cold Stress	☐ Noise*	☐ Toxic Materials*	
☐ Biohazard*	☐ Elevated Work*	☐ Hydraulic	☐ Non-ionizing Radiation	on*	
☐ Chemicals*	☐ Excavation	☐ Lasers*	☐ Oxygen Deficiency*	☐ Other	
* Does this work require medical clea	arance or surveillance from the Occu	upational Medicine Clinic? Y	es 🛛 No		
Environmental Concerns		None None	☐ Work impacts Enviro	nmental Permit No.	
☐ Atmospheric Discharges (rad/no	on-rad)	☐ Land Use	Soil	☐ Waste-Mixed	
			Activation/contamination		
☐ Chemical or Rad Material Storage	je or Use	Liquid Discharges	☐ Waste-Clean	☐ Waste-Radioactive	9
☐ Cesspools (UIC)		☐ Oil/PCB Management	☐ Waste-Hazardous	☐ Waste-Regulated	Medical
☐ High water/power consumption		Spill potential	☐ Waste-Industrial	☐ Underground Duc	/Dining
Waste disposition by:		D Opin potential	- vvaste-industrial	Other	vriping
Pollution Prevention (P2)/Waste M	linimization Opportunity:	⊠ None ☐ Yes		☐ Office	
FACILITY CONCERNS	None None	Notic Tes			
TAGILITI CONCLIUTO	☐ Electrical Noise	Potential to Cause a	Ealso Alarm	- Vibrations	
☐ Access/Egress Limitations	☐ Impacts Facility Use A		Temperature Change		
☐ Configuration Control	☐ Maintenance Work on		Utility Interruptions	e Li Otrier	
WORK CONTROLS	Maintenance Work on	ventuation dystems	Ounty interruptions		article of S
Work Practices			And the second second		METAL SERVICES
	T	☐ Lockout/Tagout			
☐ None	☐ Exhaust Ventilation	Magnet	☐ Spill Containment	☐ Security (see Instr	uction She
Back-up Person/Watch ■ Back-up Person/Watch	☐ HP Coverage	☐ Posting/Warning Signs	☐ Time Limitation	☐ Other	
☐ Barricades	☐ IH Survey	☐ Scaffolding-requires	☐ Warning Alarm (i.e. "	high love(*)	
		inspection		mgn icver j	
Protective Equipment			Search on Mary and the July	(1) - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	ta kada
⊠ None	☐ Ear Plugs	Gloves	Lab Coat	☐ Safety Glasses	
Coveralls	☐ Ear Muffs	Goggles	Respirator	☐ Safety Harness	
☐ Disposable Clothing	☐ Face Shield	☐ Hard Hat	☐ Shoe Covers	Shape	Other
				Shoes	
Permits Required (Permits must be	valid when job is scheduled.)	STATE OF STREET	7.75 - 1544	AT AN ACTION OF THE POST	445.00
Permits Required (Permits must be None			Systems		
None Non	☐ Cutting/Welding	☐ Impair Fire Protection☐ Rad Work Permit-RW	n Systems		
None Concrete/Masonry Penetration	☐ Cutting/Welding ☐ Digging/Core Drilling	Rad Work Permit-RW	n Systems		
None Concrete/Masonry Penetration Confined Space Entry	☐ Cutting/Welding	Rad Work Permit-RW	n Systems /P No		
None Concrete/Masonry Penetration Confined Space Entry Dosimetry/Monitoring	☐ Cutting/Welding ☐ Digging/Core Drilling ☐ Electrical Working Hot	☐ Rad Work Permit-RW ☐ Other	n Systems I/P No		
None Concrete/Masonry Penetration Confined Space Entry Dosimetry/Monitoring None	☐ Cutting/Welding ☐ Digging/Core Drilling ☐ Electrical Working Hot ☐ Heat Stress Monitor	Rad Work Permit-RW Other Real Time Monitor	n Systems //P No		
None Concrete/Masonry Penetration Confined Space Entry Dosimetry/Monitoring	☐ Cutting/Welding ☐ Digging/Core Drilling ☐ Electrical Working Hot	Rad Work Permit-RW Other Real Time Monitor Self-reading Pencil	n Systems I/P No	on	
None Concrete/Masonry Penetration Confined Space Entry Dosimetry/Monitoring None	☐ Cutting/Welding ☐ Digging/Core Drilling ☐ Electrical Working Hot ☐ Heat Stress Monitor	Rad Work Permit-RW Other Real Time Monitor	n Systems //P No	on	
None Concrete/Masonry Penetration Confined Space Entry Dosimetry/Monitoring None Air Effluent	☐ Cutting/Welding ☐ Digging/Core Drilling ☐ Electrical Working Hot ☐ Heat Stress Monitor ☐ Noise Survey/Dosimet	Rad Work Permit-RW Other Real Time Monitor Er Self-reading Pencil Dosimeter Self-reading Digital Dosimeter Sorbent Tube/Filter	n Systems I/P No TLD Waste Characterizati	on	
None Concrete/Masonry Penetration Confined Space Entry Dosimetry/Monitoring None Air Effluent Ground Water Liquid Effluent	☐ Cutting/Welding ☐ Digging/Core Drilling ☐ Electrical Working Hot ☐ Heat Stress Monitor ☐ Noise Survey/Dosimet ☐ O2/Combustible Gas ☐ Passive Vapor Monitor	Rad Work Permit-RW Other Real Time Monitor Self-reading Pencil Dosimeter Self-reading Digital Dosimeter	n Systems I/P No TLD Waste Characterizati	on	
None Concrete/Masonry Penetration Confined Space Entry Dosimetry/Monitoring None Air Effluent Ground Water Liquid Effluent Training Requirements (List below)	☐ Cutting/Welding ☐ Digging/Core Drilling ☐ Electrical Working Hot ☐ Heat Stress Monitor ☐ Noise Survey/Dosimet ☐ O₂/Combustible Gas ☐ Passive Vapor Monitor specific training requirements)	Rad Work Permit-RW Other Real Time Monitor Self-reading Pencil Dosimeter Self-reading Digital Dosimeter Sorbent Tube/Filter Pump	n Systems I/P No TLD Waste Characterizati		
None Concrete/Masonry Penetration Confined Space Entry Dosimetry/Monitoring None Air Effluent Ground Water Liquid Effluent Training Requirements (List below PHENIX Awareness, Confined Space	☐ Cutting/Welding ☐ Digging/Core Drilling ☐ Electrical Working Hot ☐ Heat Stress Monitor ☐ Noise Survey/Dosimet ☐ O₂/Combustible Gas ☐ Passive Vapor Monitor specific training requirements)	Rad Work Permit-RW Other Real Time Monitor Self-reading Pencil Dosimeter Self-reading Digital Dosimeter Sorbent Tube/Filter Pump	n Systems I/P No TLD Waste Characterizati		n the aeri
None Concrete/Masonry Penetration Confined Space Entry Dosimetry/Monitoring None Air Effluent Ground Water Liquid Effluent Training Requirements (List below PHENIX Awareness, Confined Space lift)	☐ Cutting/Welding ☐ Digging/Core Drilling ☐ Electrical Working Hot ☐ Heat Stress Monitor ☐ Noise Survey/Dosimet ☐ O2/Combustible Gas ☐ Passive Vapor Monitor specific training requirements).	Rad Work Permit-RW Other Real Time Monitor Self-reading Pencil Dosimeter Self-reading Digital Dosimeter Sorbent Tube/Filter Pump ift (for driving the aerial lift), working	n Systems VP No TLD Waste Characterizati Other In Systems We have the system of	on equipment (for driving or riding i	
None Concrete/Masonry Penetration Confined Space Entry Dosimetry/Monitoring None Air Effluent Ground Water Liquid Effluent Training Requirements (List below PHENIX Awareness, Confined Space	☐ Cutting/Welding ☐ Digging/Core Drilling ☐ Electrical Working Hot ☐ Heat Stress Monitor ☐ Noise Survey/Dosimet ☐ O2/Combustible Gas ☐ Passive Vapor Monitor specific training requirements).	Rad Work Permit-RW Other Real Time Monitor Self-reading Pencil Dosimeter Self-reading Digital Dosimeter Sorbent Tube/Filter Pump ift (for driving the aerial lift), working	Systems IP No TLD Waste Characterizati Other If using the permit when need to sign: (Although		the follow
None Concrete/Masonry Penetration Confined Space Entry Dosimetry/Monitoring None Air Effluent Ground Water Liquid Effluent Training Requirements (List below PHENIX Awareness, Confined Space lift) Based on analysis above, the Walle	☐ Cutting/Welding ☐ Digging/Core Drilling ☐ Electrical Working Hot ☐ Heat Stress Monitor ☐ Noise Survey/Dosimet ☐ O2/Combustible Gas ☐ Passive Vapor Monitor specific training requirements).	Rad Work Permit-RW Other Real Time Monitor Self-reading Pencil Dosimeter Self-reading Digital Dosimeter Sorbent Tube/Filter Pump ift (for driving the aerial lift), working complexity, and coordination	n Systems IP No TLD Waste Characterizati Other Other If using the permit when	on equipment (for driving or riding i	the follow
None Concrete/Masonry Penetration Confined Space Entry Dosimetry/Monitoring None Air Effluent Ground Water Liquid Effluent Training Requirements (List below: PHENIX Awareness, Confined Space lift) Based on analysis above, the Walleratings below:	Cutting/Welding Digging/Core Drilling Electrical Working Hot Heat Stress Monitor Noise Survey/Dosimet O2/Combustible Gas Passive Vapor Monitor specific training requirements) e (for working in the magnet, Aerial lickdown Team determines the risk, of	Rad Work Permit-RW Other Real Time Monitor Self-reading Pencil Dosimeter Self-reading Digital Dosimeter Sorbent Tube/Filter Pump ift (for driving the aerial lift), working te High	Systems IP No TLD Waste Characterizati Other If using the permit when need to sign: (Although form)	on equipment (for driving or riding i	the follow back of
None Concrete/Masonry Penetration Confined Space Entry Dosimetry/Monitoring None Air Effluent Ground Water Liquid Effluent Training Requirements (List below PHENIX Awareness, Confined Space lift) Based on analysis above, the Wall ratings below: ES&H Risk Level:	□ Cutting/Welding □ Digging/Core Drilling □ Electrical Working Hot □ Heat Stress Monitor □ Noise Survey/Dosimet □ O2/Combustible Gas □ Passive Vapor Monitor specific training requirements) a (for working in the magnet, Aerial lickdown Team determines the risk, of the low of	Rad Work Permit-RW Other Real Time Monitor Self-reading Pencil Dosimeter Self-reading Digital Dosimeter Sorbent Tube/Filter Pump ift (for driving the aerial lift), working the aerial lift), working the Lift of the Li	Systems IP No TLD Waste Characterizati Other If using the permit when need to sign: (Although form) WCC:	on equipment (for driving or riding i	the follow back of Date:

3, BC	Work requester and service provides Work Plan (procedures, timing, equipm See Attached						
	Special Working Conditions Required: None					200	
	Operational Limits Imposed: None						
	Post Work Testing Required: No						ALL AND ALL AN
	Job Safety Analysis Required: Yes	s ⊠ No		Walkdown Red	quired: 🗌 Yes 🛛 No		
	Reviewed by: Primary Reviewer will do means that the hazards and risks that co	etermine the size of the review to	eam and the other s	signatures require	ed based on hazards and j	ob complexity. Primary Review	ver signature
	Title	Name (print)	Signature Signature	controlled accord	Life #	Date	Maria de la como
	Primary Reviewer					MOLES OF 1277	
	ES&H Professional						
	Other		 				
	Other		1	2			
	Work Control Coordinator						
	Service Provider						
		Review Done: in series	☐ team				
4. Jo	b site personnel fill out this section.	Surface and Associated Court		Y . STREET, 7 . 7			Market State of the State of
	Note: Signature indicates personnel pe		derstand the hazar		A CORP.	attachments).	學的學樣的
	Job Supervisor:			Contractor Sup	pervisor:	T	
	Workers:	Life#:	****	Workers:		Life#:	,
					*		
					3		
	Workers are encouraged to provide feed	dback on ES&H concerns or on i	deas for improved	ob work flow. Us	se feedback form or space	below.	
5 Do	partmental Job Supervisor, Work Contr	rol Coordinator/Deciano			WEU, S	100	
U. DU	Conditions are appropriate to start work	A STATE OF THE STA	ork controls are in n	lare and eite is n	early for ioh)		
		DESTATE AND DESCRIPTION OF THE PERSON OF THE	on controls are ar p	T-162 8-120-00-5-55-9	sady for job.,		
	Name:	Signature:		Life#:		Date:	
6. De	partmental Job Supervisor, Work Requ Post Job Review (Fill in names of review	BORNES OF A STANDARD	Post Job Review is	required. 🔲	Yes No		建 加度 (12.5%)
	Name:	Signature:		Life#:		Date:	Lateral Color, Section 2
	Name:	Signature:	7	Life#:		Date:	
7 141-	rker provides feedback.	L				I management	***************************************
7. 440	Worker Feedback (use attached sheets			99			
	a) WCM/WCC: Is any feedback require	ed? Yes No					
	b) Workers: Are there better methods of	or safer ways to perform this job	in the future?	Yes 🗌 No	*		
8. Clos	seout: Work Control Coordinator (auth up of work area to work supervisor)	orizing dept.) checks quality o	f completed perm	it and ensures t	he work site is left in an	acceptable condition. (WCC	can delegate
	Name:	Signature:		Life#:		Date:	
ı	Comments:					L	

WP#		
T T M II		

Repair and/or replace FEM's inside South Muon Magnets in PHENIX IR, Bldg. 1008

South and North Muon Magnet Confined Space Entry - Class 2A: Enter the South Muon Magnet (MMS) in the experimental hall and (A) inspect for water and (B) repair/replace electronic modules (FEM Cards) as required. The detector chambers inside the MMS contain inert gas (N2). Hazardous Atmosphere Testing is not required. The hazards are that entry is made via ladder (MMS) through an opening created by removing the east vertical lampshade about 11 feet above track level and the magnet has a sloping floor (35 to 40 degree from vertical) which may present the danger of a slip/fall (about 6 feet elevation change down sloping floor). The FEM Cards which currently require repair/replacement are all accessible from an external articulated manlift and internal access is required only for inspection, unless after such inspection it is determined that internal repairs are necessary as well. The inspection will be accomplished without installing any internal steps, as adequate support from structural elements is within reach. Should internal repairs be deemed necessary, however, more stable access to work surfaces is provided by installing "steps" on the sloping floor. At all times adherence to the PHENIX "two person" rule is required: when the magnet is occupied, two people must be present and within talking distance at all times.

This work is to be done by fully trained and experienced PHENIX personnel, under the supervision of Sal Marino. A properly executed and signed Confined Space Entry (CSE) Certification is required prior to entry.

Procedure

LOTO the power to the magnet coil at the power supply in1008B. Remove the east/vertical lampshade and the lampshade immediately above it.(Pearson)

Verify that no gas is flowing to the chambers. (Biggs)

Secure a ladder to the east side of the MMS. For the MMN provide a step ladder to enter via the hatch. (Marino)

Enter either magnet and inspect for water intrusion; if any is found then install the pre-fabricated steps on the lower east lampshade panel (MMS and MMN) working from the bottom up. If access is required to any west side electronics the stairs to that side will also be installed. Work is limited to the bottom three sectors of stations 2 and 3 and the lower crates of the vertical sectors that may be easily reached from the steps. (Marino, MuTr experts)

If Necessary, enter the magnet and remove/repair/replace FEM components. When one person enters the other will provide backup watch at the entry opening/hatch. (MuTr experts) (Marino, MuTr experts)

After the internal repairs (if required) are completed, perform the rep[airs on FEM Cards accessible from the exterior via the articulated manlift. Note: only properly trained PHENIX technicians may operate the manlift and passengers in the manlift must have appropriate training in fall protection and working at heights in order to be qualified to work from the manlift. (Marino, MuTr experts)

Once work is complete, remove the internal steps, sweep the magnet interior for tools and personnel and remove the external access ladder. (Marino, MuTr experts)

Reinstall the MMS lampshades per CA Procedure (Pearson)

Remove LOTTO on magnet power supply. (Pearson)



CONFINED SPACE ENT	KY CEKTIFIC	ATION		
Location Duilding 1008 IP, Muon Magnet South (MMS)			Date	
Building 1008, IR, Muon Magnet South (MMS)	Division			
Department PO	PHENIX			
Building	Area/Location/Room:			
1008	IR, MMS			
Supervisor/Designee			Life # 20146/1576	7
Don Lynch/SalMarino	TECTIONS		20140/13/0	
PRE-ENTRY QI For each item, check "yes" or "no": If no, consult Supervisor	UESHONS	Barrier II	YES	NO
Is entry essential to perform work?				
Have all personnel been trained in confined space entry?				
Are conditions safe to remove utility-hole cover?				
Has opening been guarded?		22222		
Is monitoring equipment calibrated?				
Has monitoring been performed and recorded below?		was uther intercontrol		
Is GFCI used, if outside or in wet conditions?			0	
Is ventilation blown into bottom of space? (If required)				
Are personnel instructed to evacuate upon hazard detection?				
Have all workers reviewed these entry requirements?				
Radiation: If present, RWP may be required - review work with Es	SH Coordinator and RC	D 🗆 Re	eviewed	
personnel. Evaluate hazards and controls.				
SPACE CLASSIFICA		Class 2A	Class 2B	Class 2C
For each item, check box only if "yes"	W. Wilder H.	Class ZA	Class 2D	
Engulfment Hazard Present				
Entrapment Hazard Present				
Electrical Systems:				
Deenergized The day of the				
Energized and Working Hot				
Energized, but Guarded or not Working Hot				
Mechanical Systems:				
• Deenergized				
Energized and Working Hot				
Energized but Guarded or not Working Hot				
Other Energized Systems: (e.g., steam, sewage)				
Deenergized				
Energized and Working Hot				
Energized but Guarded or not Working Hot	autuallahla har			
Chemical Hazards inherent in space, based upon monitoring, but c ventilating				
Chemical Hazards inherent in space, based upon monitoring, but n	ot controllable by			
ventilating				
Chemical Sources, introduced into space? (e.g., welding fumes, so				
High Temperature/Pressure Hazard? (other than steam utility-holes	The state of the s			
If ANY box in column 2C is checked, a Confined Space Perm				
If any box in column 2B is checked, and none in column 2C, a	a Confined Space Permit	IS NOT req	uired BUT cor	ntinuous
monitoring and ventilating ARE required.				
 If only boxes in column 2A are checked, no additional require 				
CONTRACTOR AND	on evaluation			
CLASSIFICATION	ale of this Courfered Co	E	tian fam	and find their
I have completed the front and ba	CK OF THIS CONTINED Space	Dilliy Certifica	tion form and cla	assilied this

CLASS:2A

space. If the confined space is classified as a 2C, I will obtain a Confined Space entry permit. If the space is Class 2B, continuous monitoring and ventilation is required and will be documented on this form.

Supervisor/Designee:	Life #	Date:	Merch C.

BNL CONFINED SPACE ENTRY CERTIFICATION

Meter:			Serial #	Calibration Date:	
Day of Use Sensor Check	□ Yes	□ No			
Tested By:				BNL#:	

Tested By:		BNL Number:			
Date/ Time	Oxygen % (% O2)	Flammable Gas (% LEL)	Carbon Monoxide (CO ppm)	Hydrogen Sulfide (H2S ppm)	Other:
Pre-Entry Certification test					

Supplemental sampling record

CLASS 2B CONFINED SPACE ENTRY CERTIFICATION

For Class2B spaces, continuous monitoring is required.

			G RESULTS		
ested By:		BNL Number:			
Date/ Time	Oxygen % (% O2)	Flammable Gas (% LEL)	Carbon Monoxide (CO ppm)	Hydrogen Sulfide (H2S ppm)	Other:
				4104	
ceptable Reading	19.5 – 23.5 %	< 10 % of LEL	25 ppm	10 ppm	

Class 2B: Describe Method of Ventilation:		

Muon Magnet Confined Space Entry Certification Sheet

The undersigned certify that they have taken the BNL Confined Space Training, BNL Course # HP-OSH-016, within the last twelve months, and understand the hazards involved in working in the south and north muon magnets (MMS and MMN).

DATE	SIGNATURE	LIFE/GUEST #
11		
	8	
2000	æ	
· .		

Muon Magnet Confined Space Entry certification Sheet.

The undersigned certify that they have taken the BNL Confined Space Training within the last twelve months, and understand the hazards involved in working inside the south and north muon magnets (MMS and MMN).

DATE	SIGNATURE	LIFE/GUEST #
06/14/04	(Imran Younus)	U 8234
r.		
,		
	,	